



more at github.com/telavivmakers/at-tami

Notes:

1. D1 and D2 are Blue LEDs they might not light when using $V_{i_BAT} < 4V$ ~
2. When VCC is less than 5V change the system clock of the ATTINY85 to 8MHz or less - refer to the datasheet P163 Section 21-3 Speed

T.A.M.I hackerspace crew
LICENSE: CERN OHL 1.7

ATTAMI-Shield-soundday	
26/11/2014 13:55:57	
Sheet: 1/1	