



Notes:

1. D1 and D2 are Blue LEDs they might not light when using $V_{i_BAT} < 4V$
2. When VCC is less than 5V change the system clock of the ATTINY85 to 8MHz or less (refer to the datasheet P163 Section 21-3 Speed)

T.A.M.I hackerspace crew
 LICENSE: CERN OHL 1.7

ATTAMI-V0.00
15/04/2015 23:55:15
Sheet: 1/1